

AD-A082 112

BAI CONSULTANTS INC MONROEVILLE PA
NATIONAL DAM SAFETY PROGRAM. PENN NURSERY DAM (NDI I.D. NUMBER --ETC(U)
JAN 80 B M MIHALCIN

F/6 13/13

DACWS1-80-C-0016

NL

UNCLASSIFIED


[11]

■



END

DATE
FILMED
4-80
DTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

ADA082112

SUSQUEHANNA RIVER BASIN
POTTER RUN, CENTRE COUNTY

PENNSYLVANIA

PENN NURSERY DAM


NDI I.D. No. PA-00470

PENNDER I.D. No. 14-117

DACW 31-80-C-0016

CONTAINS COLOR PLATES: ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DTIC
ELE
S MAR 2 1 1980

PREPARED FOR

A

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

PREPARED BY

GAI CONSULTANTS, INC.
570 BEATTY ROAD
MONROEVILLE, PENNSYLVANIA 15146
JANUARY 1980

DDC FILE COPY

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.
THE COPY IS FURNISHED TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.

DISTRIBUTION STATEMENT A
Approved for public release
Distribution Unlimited

80 3 21 072

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

/

20 | Bernard M. Mihalein | 15 | IACW 31-84-C-0016

PREFACE

(11) Jan 81
G2 [82]

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

⑥ National Dam Safety Program
Penn Nursing Dam (NDE I. R.
Number PA-00475,
Penn DE R. I. R. Number 14-111),
Susquehanna River Basin,
Potter Run, Centre County,
Pennsylvania, Phase I Inspection
Report, 1

4/11/01 2

A 23

JO

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Penn Nursery Dam: NDI I.D. No. PA-00470

Owner: Commonwealth of Pennsylvania,
Department of Environmental
Resources (PennDER)

State Located: Pennsylvania (PennDER I.D. No. 14-117)

County Located: Centre

Stream: Potter Run

Inspection Date: 28 November 1979

Inspection Team: GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146

Based on a visual inspection, operational history, and available engineering data, the dam is considered to be in good condition.

> The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Due to the high potential for damage to downstream structures and possibly loss of life, the SDF is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store approximately 92 percent of the PMF prior to embankment overtopping. Based on screening criteria contained in the recommended guidelines, the spillway is considered to be inadequate, but not seriously inadequate.

> Deficiencies noted by the inspection team included a seepage condition along a portion of the downstream embankment toe approximately 160 feet to the right of the left abutment hillside and a minor vertical crack in the concrete spillway overflow wall.

It is recommended that the owner:

- a. Complete the current assessment of the seepage condition at Penn Nursery Dam and immediately implement remedial measures.

b. Fill and seal the vertical crack in the concrete spillway overflow wall.


c. Revise the current operation and maintenance manual to include a formal emergency warning system that provides for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin
Bernard M. Mihalcin, P.E.

James W. Peck
JAMES W. PECK
Colonel, Corps of Engineers
District Engineer



Date 12 Feb 1980

Date 12 March 1980

DLB:BMM/sam



OVERVIEW PHOTOGRAPH

TABLE OF CONTENTS

	<u>Page</u>
PREFACE	i
ABSTRACT.	ii
OVERVIEW PHOTOGRAPH	iv
TABLE OF CONTENTS	v
SECTION 1 - GENERAL INFORMATION	1
1.0 Authority	1
1.1 Purpose	1
1.2 Description of Project.	1
1.3 Pertinent Data.	2
SECTION 2 - ENGINEERING DATA.	6
2.1 Design.	6
2.2 Construction Records.	7
2.3 Operational Records	7
2.4 Other Investigations.	7
2.5 Evaluation.	7
SECTION 3 - VISUAL INSPECTION	8
3.1 Observations.	8
3.2 Evaluation.	9
SECTION 4 - OPERATIONAL PROCEDURES.	10
4.1 Normal Operating Procedure.	10
4.2 Maintenance of Dam.	10
4.3 Maintenance of Operating Facilities	10
4.4 Warning System.	10
4.5 Evaluation.	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION	11
5.1 Design Data	11
5.2 Experience Data	11
5.3 Visual Observations	11
5.4 Method of Analysis.	11
5.5 Summary of Analysis	11
5.6 Spillway Adequacy	12
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY.	13
6.1 Visual Observations	13
6.2 Design and Construction Techniques.	13
6.3 Past Performance.	13
6.4 Seismic Stability	13
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES	14
7.1 Dam Assessment.	14
7.2 Recommendations/Remedial Measures	14

TABLE OF CONTENTS

APPENDIX A - VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES
APPENDIX B - ENGINEERING DATA CHECKLIST
APPENDIX C - PHOTOGRAPHS
APPENDIX D - HYDROLOGY AND HYDRAULICS ANALYSES
APPENDIX E - FIGURES
APPENDIX F - GEOLOGY

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
PENN NURSERY DAM
NDI #PA-00470, PENNDER #14-117

SECTION 1
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Dam and Appurtenances. Penn Nursery Dam is a 23-foot high earth embankment approximately 600 feet long, including spillway. The facility is served by an uncontrolled, reinforced concrete, flat-crested, straight drop type overflow spillway located 150 feet from the right abutment. The length of the spillway crest is 40 feet. Drawdown capability is provided by a 2.0- by 2.5-foot rectangular concrete box culvert located at the base of the left spillway wingwall. Flow through the culvert is controlled via a sluice gate operated manually from the embankment crest.

b. Location. Penn Nursery Dam is located on Potter Run in Potter Township, Centre County, Pennsylvania. The site is located on the grounds of the Penn Nursery State Forestry, just off U. S. Route 322 approximately 15 miles southeast of State College, Pennsylvania. The dam and reservoir are contained within the Spring Mills, Pennsylvania 7.5 minute U.S.G.S. topographic quadrangles (see Figure 1, Appendix E). The coordinates of the dam are N 40° 46.6' and W 77° 37.2'.

c. Size Classification. Small (23 feet high, 293 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. Commonwealth of Pennsylvania
Department of Environmental Resources

f. Purpose. Irrigation.

g. Historical Data. Penn Nursery Dam was designed by the PennDER, Bureau of Engineering. Its purpose is to provide the major portion of the water storage needed to meet the irrigation requirements of the nursery. The facility was constructed by D. E. Smith, Inc., of Mifflintown, Pennsylvania under the supervision of the Pennsylvania Department of General Services (formerly the General State Authority) and was completed in November 1972.

Correspondence and data contained in PennDER files indicate the facility has encountered significant seepage problems during its brief history. In February 1973 seepage was first reported along the downstream embankment toe to the left of the spillway. No soil movement was evident and it was observed that seepage ceased at pool levels below elevation 1489 feet (4 feet below normal pool). At that time it was speculated that the seepage was due to the lack of a suitable cutoff beneath the left side of the embankment. Subsequently, the pool was drawn down and a graded filter placed at the downstream embankment toe. In 1974 the seepage condition was reportedly stabilized and apparently did not reoccur until June 1978 when it was reported that the area at the downstream embankment toe to the left of the spillway had become wet. Three months later it was reported that a definite increase in the rate of seepage was evident and that a serious condition may be developing. Fine earth materials were observed to have been deposited along the toe. Once again, the reservoir level was lowered, this time by 2 feet, to ensure safety. The problem has not been resolved to date. However, the PennDER is actively pursuing the various alternatives available.

1.3 Pertinent Data.

a. Drainage Area (square miles). 3.1

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Rating curves provided in Appendix D (Sheet 11).

Discharge Capacity of Spillway at Maximum Pool \approx 4210 cfs (see Appendix D, Sheet 6).

c. Elevation (feet above mean sea level). The following elevations were obtained from available drawings and

through field measurements based on the elevation of the spillway crest at 1493 feet (see Appendix D, Sheet 2, Note 1).

Top of Dam	1503
Maximum Design Pool	1502
Maximum Pool of Record	Not known
Normal Pool	1493
Spillway Crest	1493
Upstream Outlet Invert	1480.5
Downstream Outlet Invert	1480
Streambed at Dam Centerline	Not known
Maximum Tailwater	Not known

d. Reservoir Length (feet).

Top of Dam	2000
Normal Pool	1400

e. Storage (acre-feet).

Top of Dam	293
Normal Pool	54
Design Pool	234
Design Surcharge	59

f. Reservoir Surface (acres).

Top of Dam	32
Normal Pool	12
Maximum Design Pool	29

g. Dam.

Type	Homogeneous rolled earth.
Length	560 feet (excluding spillway).
Height	23 feet (field measured; base of stilling basin to top of embankment crest).
Top Width	15 feet.
Upstream Slope	2H:1V

Downstream Slope	2H:1V
Zoning	Homogeneous earth.
Impervious Core	None indicated.
Cutoff	Design drawings indicate a partial cutoff trench excavated to rock along embankment centerline, to the right of the spillway, 10 feet wide at base with 1H:1V side slopes.
Grout Curtain	None indicated.
h. <u>Diversion Canal and Regulating Tunnels.</u>	None.
i. <u>Spillway.</u>	
Type	Uncontrolled, reinforced concrete, flat-crested, straight drop type spillway.
Crest Elevation	1493 feet.
Crest length	40 feet.
j. <u>Outlet Conduit.</u>	
Type	2.0- by 2.5-foot concrete box culvert located at base of left spillway wingwall.
Length	13 feet.
Closure and Regulating	Flow through the culvert is controlled via sluice gate operated manually from the embankment crest.

Access

Manually operated draw-down control mechanism is accessible from the left abutment.

SECTION 2 ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources. No formal design reports or calculations are available for any aspect of the facility. Design drawings, contract specifications, and miscellaneous design data are contained in PennDER files. A formal operation and maintenance manual dated January 1973 by PennDER discusses design features of the facility in detail.

b. Design Features.

1. Embankment. Available data indicates the embankment is a homogeneous earth fill. A partial cutoff trench excavated to rock is provided along the embankment centerline to the right of the spillway. The upstream and downstream embankment faces are both sloped at 2H:1V. Dumped limestone riprap protects the upstream slope against wave action while the rest of the embankment is grass covered. The top width of the fill is 15 feet. Drawings indicate a foundation drainage blanket and toe drain have been provided (see Figures 2 and 3).

2. Appurtenant Structures.

a) Spillway. The spillway is an uncontrolled, reinforced concrete, straight drop overflow type structure. The crest is 40 feet long and set 10 feet below the top of the wingwalls. A reinforced concrete stilling basin is provided immediately below the weir. It measures 40 feet by 40 feet and has a 2-foot high end sill (see Figure 4).

b) Outlet Conduit. The outlet conduit is incorporated into the spillway structure and is situated at the base of the left wingwall. The conduit is a 2.0- by 2.5-foot concrete box culvert, 13 feet long, that discharges into the base of the stilling basin. Flow through the outlet is controlled via 24-inch slide gate at its inlet end.

c. Specific Design Data and Criteria.

1. Hydrology and Hydraulics. No formal design reports or calculations are available. Information contained in PennDER files indicates the spillway was designed to discharge a flow of 3390 cfs while providing a freeboard of 1-foot. A formal manual by PennDER, Division of Completed Projects, entitled "Operation and Maintenance Manual for

Penn Nursery Irrigation Dam" dated January 1973 is available at the main office of the nursery. The manual contains miscellaneous design information on the entire facility as well as outlet conduit and spillway rating curves, and a reservoir area-capacity curve.

2. Embankment. Available design data are limited to general information contained in the operation and maintenance manual, design drawings, contract specifications, and correspondence from PennDER files. Standard compaction curves for five borrow area samples are presented in the design drawings with detailed logs of borings and test pits.

3. Appurtenant Structures. Design data are limited to general information contained in PennDER files as stated above. Correspondence indicates that the facility is provided with an Armco medium duty sluice gate (24-inch by 24-inch) and Armco "CPE-2" manual lift mechanism.

2.2 Construction Records.

Design drawings, contract specifications and construction progress reports are contained in PennDER files.

2.3 Operational Records.

No records of the day-to-day operation of the facility are maintained.

2.4 Other Investigations.

The owner through the PennDER, Division of Completed Projects, is currently investigating seepage conditions at the facility. The seepage was originally observed and assessed in 1973. Correspondence related to the problem are contained in PennDER files.

2.5 Evaluation.

The data available are considered adequate to make a reasonable Phase I assessment of the facility.

SECTION 3
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the facility suggests it to be well maintained and in good condition.

b. Embankment. Observations made during the visual inspection indicate the embankment is in good condition. No evidence of sloughing, excess settlement, animal burrows, or signs of maintenance neglect were observed (see Photograph 1 and 2).

As indicated previously in Section 1.2.g., the facility has experienced a seepage condition at the left abutment for several years. On the day of the inspection, the field team observed a drainage trench that had been excavated several feet downstream of the left abutment toe (see Photograph 6). The trench is approximately 100 feet long and is cut about 160 feet to the right of the extreme left abutment contact. The trench was apparently dug in an effort to evaluate the seepage condition along the downstream embankment toe where fine materials were observed. A v-notch weir has been installed to facilitate measurement of seepage. The field team estimated the current rate of seepage at about 30 gpm. A wet condition still exists in the immediate toe area (see Photograph 5); however, no seepage was observed through the downstream embankment face.

c. Appurtenant Structures.

1. Spillway. The visual inspection revealed that the spillway is in good condition. A vertical crack near the center of the concrete overflow was the only evidence of concrete deterioration observed by the inspection team (see Photographs 3 and 7).

2. Outlet Conduit. At the time of inspection, the outlet conduit was inundated and discharging in an effort to maintain a low pool level (see Photographs 3 and 4).

d. Reservoir Area. The general area surrounding the reservoir is composed of approximately equal portions of wooded and grassy hillsides with moderate slopes. No signs of slope distress were observed.

e. Downstream Channel. The stream (Potter Run), into which the spillway discharges, flows in a generally northerly

direction through a narrow, wooded valley that essentially parallels U. S. Route 322. At a distance of about 1.2 miles downstream of the embankment, Potter Run passes four residences which have been constructed in close proximity to the streambed. Potter Run, in this area, is a swift moving stream on a steep grade. Further downstream, approximately 1.7 miles from the embankment, Potter Run passes directly through the community of Potters Mills, Pennsylvania. It is estimated that in the reach between Penn Nursery Dam and Potters Mills an embankment breach could result in a substantial loss of life and extensive property damage. As many as 50 persons could be affected by such an event. Consequently, the hazard classification of this facility is considered to be high.

3.2 Evaluation.

The overall condition of the facility is considered to be good. Deficiencies noted by the inspection team include seepage along the downstream embankment toe and a minor vertical crack in the concrete spillway overflow wall.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

According to the operation and maintenance manual, Penn Nursery Dam is designed to be essentially self-regulating with excess inflows being automatically discharged over the emergency spillway. During periods of low flow in the dry summer months, a 2-inch diameter opening near the center base of the spillway carries sufficient flow to support fish life in the stream below the dam. The 2.0- by 2.5-foot outlet conduit is not designed to maintain low flow requirements, but to provide drawdown capability. Typically, the sluice gate that controls flow through the conduit is opened twice yearly to ensure its operability. In recent months the gate has remained partially open in order to maintain a low pool due to the seepage condition at the downstream embankment toe.

4.2 Maintenance of Dam.

The dam as designed requires only limited maintenance which is performed by Penn Nursery staff in accordance with the procedures and guidelines set forth in the operation and maintenance manual.

4.3 Maintenance of Operating Facilities.

See Section 4.2 above.

4.4 Warning System.

No formal system is in effect that would provide for the warning of downstream residents during an embankment emergency.

4.5 Evaluation.

As noted during the visual inspection, the facility appears to be well maintained. A formal operation and maintenance manual is available; however, it is recommended that the current manual be revised to include a formal emergency warning system that provides for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No formal design reports or calculations are available. Information contained in PennDER files indicates the spillway was designed to discharge a flow of 3390 cfs while providing a freeboard of 1-foot. The operation and maintenance manual contains some design information including outlet conduit and spillway rating curves, and a reservoir area-capacity curve. Data from the available rating curves is considered valid and was used in the analysis contained in Appendix D.

5.2 Experience Data.

Daily records of reservoir levels and/or spillway discharge are not available.

5.3 Visual Observations.

On the date of the inspection, no conditions were observed that would indicate the spillway could not perform satisfactorily during a flood event within the limits of its design capacity.

5.4 Method of Analysis.

The facility has been analyzed in accordance with procedures and guidelines established by the U. S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U. S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix D.

5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Penn Nursery Dam

ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. This classification is based on the relative size of the dam (small), and the potential hazard of dam failure to downstream developments (high). Due to the high potential for damage to downstream residences and possibly loss of life, the SDF for this facility is considered to be the PMF.

b. Results of Analysis. Penn Nursery Dam was evaluated under near normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of 1493 feet (MSL), with the spillway weir discharging freely. However, the usually discharging outlet conduit was assumed to be non-functional for the purpose of analysis. In any event, the flow capacity of the outlet conduit is not such that it would significantly increase the total discharge capabilities of the facility. The spillway is an uncontrolled, reinforced concrete, straight drop overflow type structure. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix D.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Penn Nursery Dam can accommodate about 92 percent of the PMF (SDF) prior to overtopping of the embankment (Appendix D, Summary Input/Output Sheets, Sheet C). The peak PMF inflow of approximately 4905 cfs was slightly attenuated by the discharge/storage capabilities of the dam and reservoir such that the resulting peak PMF outflow was about 4860 cfs (Summary Input/Output Sheets, Sheets B and C). Under the PMF, the embankment would be overtopped for approximately 2.5 hours, with a maximum depth of inundation equal to about 0.5 feet above the low top of dam elevation of 1503.0 feet (Summary Input/Output Sheets, Sheet C).

5.6 Spillway Adequacy.

Although Penn Nursery Dam cannot accommodate its SDF (the PMF), the possible downstream consequences of embankment failure due to overtopping were not evaluated. In accordance with Corps directive ETL-1110-2-234, breaching analysis was not performed, since the facility can safely pass a flood of at least 1/2 PMF magnitude. Since Penn Nursery Dam cannot accommodate a PMF-size flood, its spillway is considered to be inadequate, but not seriously inadequate.

SECTION 6
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations the embankment is in good condition. The seepage condition noted at the left abutment is presently the only major concern and should be rectified as quickly as possible. It was noted that the owner is currently investigating the condition and remedial recommendations are expected soon. The reservoir level is being maintained below normal pool to curtail seepage.

b. Appurtenant Structures.

1. Spillway. Visual observations indicate the spillway is in good condition. The vertical crack noted in the overflow wall should be filled immediately to preclude further concrete deterioration and corrosion of the reinforcing.

2. Outlet Conduit. The outlet conduit was functioning during the inspection and was totally inundated.

6.2 Design and Construction Techniques.

Correspondence, specifications, contract drawings, and construction progress reports indicate that the facility was designed and constructed in accordance with generally accepted practices.

6.3 Past Performance.

According to available correspondence and discussions with representatives of the owner, the facility has performed satisfactorily since its completion with the exception of the persistent seepage along the left abutment-embankment contact.

6.4 Seismic Stability.

The dam is located in Seismic Zone No. 1 and may be subject to minor earthquake induced dynamic forces. As the facility appears well constructed and sufficiently stable, it is believed that it can withstand the expected dynamic forces; however, no calculations and/or investigations were performed to confirm this belief.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection suggests the facility is well maintained and in good condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Due to the high potential for damage to downstream structures and possibly loss of life, the SDF for the facility is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store approximately 92 percent of the PMF prior to embankment overtopping. Based on screening criteria contained in the recommended guidelines, the spillway is considered to be inadequate, but not seriously inadequate.

Deficiencies noted by the inspection team included a seepage condition along a portion of the downstream embankment toe approximately 160 feet to right of the extreme left abutment and a vertical crack in the concrete spillway overflow wall.

b. Adequacy of Information. The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. The recommendations listed below should be implemented immediately.

d. Necessity for Additional Investigations. An investigation of the seepage condition is currently in progress. No additional investigations are currently deemed necessary.

7.2 Recommendations/Remedial Measures.

It is recommended that the owner:

a. Complete the current assessment of the seepage condition at Penn Nursery Dam and immediately implement remedial measures.

b. Fill and seal the vertical crack in the concrete spillway overflow wall.

c. Revise the current operation and maintenance manual to include a formal emergency warning system that provides for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

APPENDIX A

VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES

CHECK LIST VISUAL INSPECTION PHASE 1

NAME OF DAM Penn Nursery Dam STATE Pennsylvania COUNTY Centre

NDI # PA 00470 PENNDR # 14-117

TYPE OF DAM Earth SIZE Small HAZARD CATEGORY High

DATE(S) INSPECTION 28 November 1979 WEATHER Overcast TEMPERATURE 30° @ 9:00 a.m.

POOL ELEVATION AT TIME OF INSPECTION 1491.1 M.S.L.

TAILWATER AT TIME OF INSPECTION - M.S.L.

INSPECTION PERSONNEL

B. M. Mihalcin

D. J. Spaeder

D. L. Bonk

OWNER REPRESENTATIVES

Penn Nursery Personnel

C. Cooper (Superintendent)

OTHERS

RECORDED BY D. L. Bonk

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
SUF:FACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None observed.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal - Good. Vertical - Good.	
RIPRAP FAILURES	Dumped limestone riprap, apparently functioning adequately, but some weathering evident.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good condition.	

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
DAMP AREAS IRREGULAR VEGETATION (LUSH OR DEAD PLANTS)	Toe along left abutment is saturated with evidence of fines.	
ANY NOTICEABLE SEEPAGE	Evidence of prior seepage along toe of left abutment. Drainage ditch cut parallel to toe about 15 feet from embankment. Seepage being monitored by PennDER, Bureau of Design.	
STAFF GAGE AND RECORDER	None.	
DRAINS	None observed. Exit of toe drain was submerged.	

OUTLET WORKS

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
INTAKE STRUCTURE	Submerged, not observed.	
OUTLET CONDUIT (CRACKING AND SPALLING OF CON- CRETE SURFACES)	Same as above.	
OUTLET STRUCTURE	Same as above.	
OUTLET CHANNEL	Flow through the outlet is discharged into the spillway stilling basin and ultimately into the stream below.	
GATE(S) AND OPERA- TIONAL EQUIPMENT	Sluice gate operated by manual lift mechanism. Lift mechanism in excellent condition. Gate partially opened to maintain pool in drawdown status.	

EMERGENCY SPILLWAY

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
TYPE AND CONDITION	Reinforced concrete, flat crested, straight drop overflow type structure located 150 feet from right abutment in good condition. Vertical crack observed near the center of the concrete overflow wall.	
APPROACH CHANNEL	N/A.	
SPILLWAY CHANNEL AND SIDEWALLS	Concrete wingwalls in excellent condition. No evidence of external deterioration was observed.	
STILLING BASIN PLUNGE POOL	Reinforced concrete stilling basin located immediately below overflow weir. Excellent condition.	
DISCHARGE CHANNEL	The channel beyond the stilling basin is unlined and trapezoidal in shape. It extends approximately 400 feet to the original stream channel.	
BRIDGE AND PIERS EMERGENCY GATES	None.	

SERVICE SPILLWAY


ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
TYPE AND CONDITION	N/A.	
APPROACH CHANNEL	N/A.	
OUTLET STRUCTURE	N/A.	
DISCHARGE CHANNEL	N/A.	

INSTRUMENTATION

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA. 00470
MONUMENTATION SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	Plywood V-notch weir in drainage trench along left abutment. Flow estimated to be 30 gpm.	
PIEZOMETERS	None.	
OTHERS	None.	

RESERVOIR AREA AND DOWNSTREAM CHANNEL


ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 00470
SLOPES: RESERVOIR	The general area surrounding the reservoir is composed of approximately equal portions of wooded and grassy hillsides with moderate slopes.	
SEDIMENTATION	None observed.	
DOWNSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.)	Beyond the dam Potter Run flows in a generally northerly direction through a narrow, wooded valley that essentially parallels U. S. Route 322. The stream passes directly through the community of Potters Mills, Pennsylvania, about 1.7 miles downstream of the embankment.	
SLOPES: CHANNEL VALLEY	Narrow, wooded valley with steep confining slopes. The slope of the streambed is also steep.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	It is estimated that in the reach between the dam and Potters Mills as many as 50 persons that could be affected by an embankment breach.	



PENN NURSERY DAM
GENERAL PLAN - FIELD INSPECTION NOTES

PENN NURSERY DAM

PROFILE OF DAM CREST
FROM FIELD SURVEY



APPENDIX B
ENGINEERING DATA CHECKLIST

**CHECK LIST
ENGINEERING DATA
PHASE I**

NAME OF DAM Penn Nursery Dam

ITEM	REMARKS	NDI# PA - 00470
PERSONS INTERVIEWED AND TITLE	Charles Cooper - Penn Nursery Superintendent	
REGIONAL VICINITY MAP	See Appendix E, Figure 1.	
CONSTRUCTION HISTORY	Designed by PennDER, Bureau of Engineering. Constructed by D. E. Smith, Inc. of Mifflintown, Pennsylvania. Daily inspection provided by the General State Authority (GSA). Completed in November 1972.	
AVAILABLE DRAWINGS	Set of 5 design drawings by PennDER, Bureau of Engineering. Dated April 1971 are contained in PennDER files.	
TYPICAL DAM SECTIONS	See Appendix E, Figure 3.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Appendix E, Figure 4. See Appendix E, Figure 5. See Appendix D, Sheet 11.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA - 00470
SPILLWAY: PLAN SECTION DETAILS	See Appendix E, Figure 2. See Appendix E, Figure 4. See Appendix E, Figure 4.	
OPERATING EQUIP- MENT PLANS AND DETAILS	See Appendix E, Figure 5. Shop Drawings and specifications for slide gate and control mechanism are contained in the operation and maintenance manual.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	No formal reports are available. Significant geologic data are contained in PennDER files (see Appendix F).	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	No formal reports or calculations are available. Outlet and spillway rating curves as well as a reservoir area-capacity curve are contained in the operation and maintenance manual.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	Boring logs depicted on Drawing 2 of 5 (S-2) of design set (not included in Appendix E).	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA - 00470
BORROW SOURCES	Within reservoir.	
POST CONSTRUCTION DAM SURVEYS	None.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Seepage at left abutment is presently being assessed by the PennDER. No formal report is expected.	
HIGH POOL RECORDS	No formal records are maintained.	
MONITORING SYSTEMS	Plywood V-Notch weir (90°) is being used to monitor seepage. PennDER, Bureau of Design has the records. Rain gauge is located adjacent the nursery office and is read daily.	
MODIFICATIONS	None, except for seepage control measures along downstream toe to left of spillway.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA - 00470
PRIOR ACCIDENTS OR FAILURES	None.	
MAINTENANCE: RECORDS MANUAL	Formal manual at nursery office.	
OPERATION: RECORDS MANUAL	Formal manual at nursery office.	
OPERATIONAL PROCEDURES	Self-regulating.	
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	None.	
MISCELLANEOUS		

GAI CONSULTANTS, INC.

**CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA**

NDI ID # 00470
PENNDER ID # 14-117

SIZE OF DRAINAGE AREA: 3.1 square mile
ELEVATION TOP NORMAL POOL: 1493 STORAGE CAPACITY: 54 acre-feet
ELEVATION TOP FLOOD CONTROL POOL: - STORAGE CAPACITY: -
ELEVATION MAXIMUM DESIGN POOL: 1502 STORAGE CAPACITY: 234 acre-feet
ELEVATION TOP DAM: 1503 STORAGE CAPACITY: 293 acre-feet

SPILLWAY DATA

CREST ELEVATION: 1493 feet.
TYPE: Uncontrolled, reinforced concrete, rectangular, straight drop.
CREST LENGTH: 40 feet.
CHANNEL LENGTH: 54 feet.
SPILLOVER LOCATION: 150 feet from right abutment.
NUMBER AND TYPE OF GATES: None.

OUTLET WORKS

TYPE: 2.0-by 2.5-foot concrete box culvert.
LOCATION: Base of spillway left wingwall.
ENTRANCE INVERTS: 1480.5 feet.
EXIT INVERTS: 1480 feet.
EMERGENCY DRAWDOWN FACILITIES: 24-inch slide gate.

HYDROMETEOROLOGICAL GAGES

TYPE: rain gauge.
LOCATION: Adjacent to nursery office.
RECORDS: Daily.
MAXIMUM NON-DAMAGING DISCHARGE: Not known.

APPENDIX C
PHOTOGRAPHS

PHOTOGRAPH 1 View of the embankment and surrounding watershed.

PHOTOGRAPH 2 View of the upstream face of the embankment as seen from the left abutment.

PHOTOGRAPH 3 View of the spillway and outlet control mechanism atop the left wingwall.


PHOTOGRAPH 4 Close-up view of outlet control mechanism.




2



4



1



3

PHOTOGRAPH 5 View of the wet area along downstream toe of left abutment.

PHOTOGRAPH 6 View of recently excavated drainage trench located 15 feet downstream and parallel to the toe of the left abutment.

PHOTOGRAPH 7 View of the spillway, looking upstream.

PHOTOGRAPH 8 View of the area immediately downstream of the embankment.




6



8



5



7

APPENDIX D
HYDROLOGY AND HYDRAULICS ANALYSES

PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir.
- c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.
- d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.

HYDROLOGY AND HYDRAULIC ANALYSIS DATA BASE

NAME OF DAM: PENN NURSERY DAM

PROBABLE MAXIMUM PRECIPITATION (PMP) = 22.2 INCHES/24 HOURS ⁽¹⁾

STATION	1	2	3
STATION DESCRIPTION	PENN NURSERY DAM		
DRAINAGE AREA (SQUARE MILES)	3.1		
CUMULATIVE DRAINAGE AREA (SQUARE MILES)	-		
ADJUSTMENT OF PMF FOR DRAINAGE AREA LOCATION (%) ⁽¹⁾			
6 HOURS	121		
12 HOURS	131		
24 HOURS	140		
48 HOURS	147		
72 HOURS	149		
SNYDER HYDROGRAPH PARAMETERS			
ZONE (2)	18		
C _p (3)	0.50		
C _t (3)	2.10		
L (MILES) (4)	3.8		
L _{ca} (MILES) (4)	1.9		
t _p = C _t (L · L _{ca}) ^{0.3} (HOURS)	3.8		
SPILLWAY DATA			
CREST LENGTH (FEET)	40		
FREEBOARD (FEET)	10		

(1) HYDROMETEOROLOGICAL REPORT 40, U.S. WEATHER BUREAU, 1965.

(2) HYDROLOGIC ZONE DEFINED BY CORPS OF ENGINEERS, BALTIMORE DISTRICT, FOR DETERMINATION OF SNYDER COEFFICIENTS (C_p AND C_t).

(3) SNYDER COEFFICIENTS

(4) L = LENGTH OF LONGEST WATERCOURSE FROM DAM TO BASIN DIVIDE.

L_{ca} = LENGTH OF LONGEST WATERCOURSE FROM DAM TO POINT OPPOSITE BASIN CENTROID.

SUBJECT DAM SAFETY INSPECTION

PENNA NURSERY DAM

BY DES DATE 12-31-79 PROJ. NO. 79-203-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 1 OF 12



Engineers • Geologists • Planners
Environmental Specialists

DAM STATISTICS

- HEIGHT OF DAM = 23 FT

(FIELD MEASUREMENT)

- NORMAL POOL STORAGE CAPACITY = 54 ACRE-FT

(NOTE 1)

- MAXIMUM POOL STORAGE CAPACITY = 293 ACRE-FT
(@ LOW TOP OF DAM)

(NOTE 1)

- DRAINAGE AREA = 3.1 SQUARE MILES

{ PLANNIMETERED ON USGS 7.5 MINUTE
TWO QUADS: CENTRE HILL,
SPRING MILLS, BARRVILLE PA }

- ELEVATION OF TOP OF DAM (DESIGN) = 1503.0

(SEE NOTE 1)

- ELEVATION OF TOP OF DAM (FIELD) = 1503.0

- NORMAL POOL ELEVATION = 1472.0

(SEE NOTE 1)

- UPSTREAM INLET INVERT ELEVATION = 1480.5

(SEE NOTE 1)

- DOWNSTREAM OUTLET INVERT (DESIGN) = 1480.0

(SEE NOTE 1)

- DOWNSTREAM OUTLET INVERT (FIELD) = 1480.0

- STREAMBED AT DAM CENTRALINE = 1480.0

SUBJECT DAM SAFETY INSPECTION
PENN NURSERY DAM
 BY DJS DATE 12-31-79 PROJ. NO. 79-332-770
 CHKD. BY DLB DATE 1-2-80 SHEET NO. 2 OF 2



NOTE 1: TAKEN FROM "OPERATION AND MAINTENANCE MANUAL FOR PENN NURSERY IRRIGATION DAM, SEATTLE COUNTY, PENNSYLVANIA". FROM THE 1965 TOPO QUAD, SPRING MILLS, PA, IT IS APPARENT THAT THE ELEVATIONS REPORTED IN THIS MANUAL ARE IN ERROR. NORMAL POOL IS REPORTED TO BE AT ELEVATION 1511.0, WHEREAS THE TOPO MAP INDICATES NORMAL POOL IS SOMEWHERE BELOW ELEVATION 1500. AT ELEVATION 1500, THE SURFACE AREA IS 25 ACRES, AS PLANIMETERED ON THE TOPO. THE AREA VS. ELEVATION CURVE GIVEN IN THE MANUAL INDICATES A SURFACE AREA OF 25 ACRES OCCURS AT ELEVATION 1518.0. THUS, IT WILL BE ASSUMED THAT ALL ELEVATIONS REPORTED IN THE MANUAL ARE HIGH BY 18.0 FEET. THEREFORE, NORMAL POOL WILL BE ASSUMED AT 1511-18, OR 1493 FEET, WHICH DOES CORRELATE WITH THE TOPO MAP. (NOTE: THE ELEVATIONS LISTED IN THIS ANALYSIS ARE CONSIDERED ESTIMATES AND ARE NOT NECESSARILY ACCURATE.)

DAM CLASSIFICATION

DAM SIZE: SMALL (REF 1, TABLE 1)

HABARD CLASSIFICATION: HIGH (FIELD OBSERVATION)

REQUIRED SDF: $\frac{1}{2}$ PMF to PMF (REF 1, TABLE 2)

HYDROGRAPH PARAMETERS

- LENGTH OF LONGEST WATERCOURSE: $L = \underline{3.8}$ MILES

- LENGTH OF LONGEST WATERCOURSE FROM DAM TO A POINT DOWNSTREAM BASIN CENTROID:

$L_{CA} = \underline{1.1}$ MILES

{ MEASURED ON 1965 TOPO MAP
 CENTER LINE OF MAIN CHANNEL
 FROM DAM TO BASIN CENTROID

SUBJECT DAM SAFETY INSPECTIONS

PENN NURSERY DAM

BY DJS DATE 12-31-79 PROJ. NO. 79-303-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 3 OF 12



Engineers • Geologists • Planners
Environmental Specialists

$$C_e \approx \underline{2.10}$$

$$C_p \approx \underline{2.50}$$

(SUPPLIED BY CDE, ZONE 18,
JUNIPERHILL RIVER CO., N)

SNYDER'S STANDARD LAG:
$$t_p = C_e (L \cdot L_{co})^{0.3}$$

$$= (2.10) (3.8 \times 1.9)^{0.3}$$

$$= \underline{3.8} \text{ HOURS}$$

(NOTE: HYDROGRAPH VARIABLES USED HERE ARE DEFINED IN REFERENCE 3, IN SECTION ENTITLED "SNYDER SYNTHETIC UNIT HYDROGRAPH".)

RESERVOIR CAPACITY

- RESERVOIR SURFACE AREAS ABOVE TOP OF DAM:

$$SA_{1503} = 31.5 \text{ ACRES}$$

$$SA_{1500} = 54 \text{ ACRES}$$

(SEE NOTE 1)

(PLANIMETERED ON USGS TOPO SHEET:
CENTRE HALL, SPRING HILLS, THURMOND,
PA)

- ASSUME THAT THE MODIFIED PRISMATICAL RELATIONSHIP ADEQUATELY MODELS THE SURFACE AREA - STORAGE RELATIONSHIP ABOVE ELEVATION 1503.

(REF 14, p. 5)

$$EV_{1-2} \approx \frac{h}{3} (A_1 + A_2 + \sqrt{A_1 \cdot A_2})$$

WHERE

EV_{1-2} = INSTANTANEOUS VOLUME BETWEEN ELEVATIONS 1 & 2 (AC-FT)

h = ELEVATION 1 - ELEVATION 2 (FEET)

A_1 = SURFACE AREA @ ELEV 1 (ACRES)

A_2 = SURFACE AREA @ ELEV 2 (ACRES)

SUBJECT DAM SAFETY INSPECTION

PEWEE NURSERY DAM

BY DJS DATE 12-21-79 PROJ. NO. 79-003-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 4 OF 12



Engineers • Geologists • Planners
Environmental Specialists

ALSO, ASSUME THAT THE SURFACE AREA VARIES LINEARLY BETWEEN
ELEVATIONS 1503 AND 1520:

$$\begin{aligned} A_c &= A_{1503} + \left(\frac{\Delta SA}{\Delta H} \times H \right) \\ &= 31.5 + \left(\frac{54-31.5}{1520-1503} \times H \right) \\ &= 31.5 + 1.32 H \end{aligned}$$

WHERE $H = \text{ELEV } c - 1503 \text{ (FT)}$

ELEVATION - STORAGE RELATIONSHIP:

RESERVOIR ELEVATION (FT)	A_c (ACRES)	ΔV_{1-2} (AC-FT)	TOTAL * VOLUME (AC-FT)
1480.5			0
1486.0			4
1488.0			12
1490.0			25
1492.0			43
(NORMAL POOL) 1493.0			54
1495.0			80
1497.0			114
1499.0			156
1501.0			204
(LOW TOP OF DAM) 1503.0	31.5		243
1504.0	32.8	23.1	265
1506.0	35.5	29.3	293
1508.0	38.1	36.6	327
1510.0	40.7	43.8	366

* VOLUMES FOR ELEVATIONS AT OR BELOW ELEVATION 1503 TAKEN FROM ELEVATION -
STORAGE CURVE (SEE NOTE 1).

SUBJECT DAM SAFETY INSPECTION

PENNY NURSERY DAM

BY DJS DATE 12-31-79 PROJ. NO. 79-333-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 5 OF 12



Engineers • Geologists • Planners
Environmental Specialists

PMP CALCULATIONS

- FROM REFERENCE 9, FIGURE 2, OBTAIN PMP VALUES FOR A DRAINAGE AREA 300 SQUARE MILES, FOR A DURATION OF 24 HOURS:

$$PMP = \underline{22.2 \text{ INCHES}}$$

- FROM REF. 9, FIGURE 1, THE GEOGRAPHIC ADJUSTMENT FACTOR \approx 103%

- AREA CORRECTION FACTOR (REF 9):

DURATION (HOURS):	6	12	24	48	72
FACTOR (%) :	117.5	127.0	136.0	145.5	150.0

- TOTAL CORRECTION FACTOR ($1.03 \times$ AREA CORRECTION FACTOR):

DURATION (HRS):	6	12	24	48	72
FACTOR (%) :	121	131	140	147	149

- HOP CRACK FACTOR (ADJUSTMENT FOR CATCH BASIN AND FOR THE LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALL DRAIN) FOR A DRAINAGE AREA OF 31 SQUARE MILES IS 2.22.

SUBJECT DAM SAFETY INSPECTION

PEWEE NURSERY DAM


BY 2JS DATE 12-31-79 PROJ. NO. 79-203-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 6 OF 12

gai
CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental Specialists

SPILLWAY CAPACITY



(BASED ON FIELD NOTES)

- DISCHARGE IS CONTROLLED BY A STRAIGHT-DROP CONCRETE SPILLWAY, WITH CREST AT ELEVATION 1493.0. A SPILLWAY RATING CURVE WAS PROVIDED IN THE OPERATION AND MAINTENANCE MANUAL (SEE NOTE 1), FROM WHICH THE FOLLOWING DATA WERE OBTAINED:

SPILLWAY RATING TABLE:

RESERVOIR ELEVATION (FT)	DISCHARGE (CFS)	RESERVOIR ELEVATION (FT)	DISCHARGE (CFS)
1493.0	0	1503.0	3590
1494.0	110	(LOW TOP OF DAM) 1503.0	4310
1495.0	340	1504.0	4820
1496.0	670	1505.0	5540
1497.0	1060	1506.0	6240
1498.0	1480	1507.0	6930
1499.0	1950	1508.0	740
1500.0	2440	1509.0	8590
1501.0	3000	1510.0	9440

SUBJECT DAM SAFETY INSPECTION

FRANKLIN DAM

BY DT DATE 12-31-79 PROJ. NO. 79-203-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 7 OF 12



Engineers • Geologists • Planners
Environmental Specialists

* $\rightarrow Q = CLH^{3/2}$, $C = 3.33$, $L = 40$ FT, $H = \text{RES ELEV} - 1493.0$
(C-VALUE CONSISTENT WITH THAT USED IN RATING CURVE.)

EMBANKMENT RATING CURVE

- ASSUME THAT THE EMBANKMENT BEHAVES ESSENTIALLY AS A
BROAD-CRESTED WEIR WHEN OVERTOPPING OCCURS. THUS, THE DISCHARGE
CAN BE ESTIMATED BY THE RELATIONSHIP

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE Q = DISCHARGE OVER EMBANKMENT (CFS)

L = LENGTH OF EMBANKMENT INUNDATED (FT)

H = HEAD ON WEIR; IN THIS CASE, IT IS THE AVERAGE

"FLOW-AREA" WEIGHTED HEAD ABOVE THE CREST, USING THE
LOW TOP OF DAM AS THE DATUM. (FEET)

C = COEFFICIENT OF DISCHARGE, DEPENDENT ON HEAD AND WEIR DESIGN.

LENGTH OF EMBANKMENT INUNDATED VS. RESERVOIR ELEVATION:

ELEVATION (FT)	LENGTH (FT)	ELEVATION (FT)	LENGTH (FT)
1503.0	0	1504.0	610
1503.1	170	1505.0	630
1503.2	400	1506.0	630
1503.3	500	1507.0	640
1503.5	550	1508.0	660
1503.7	600	1509.0	680

(BASED ON FIELD
MEASUREMENTS &
JES TOWN SPRINGS
MILLS, PA.)

SUBJECT DAM SAFETY INSPECTION

PENN NURSERY DAM

BY DJS DATE 12-31-79 PROJ. NO. 79-202-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 8 OF 12



Engineers • Geologists • Planners
Environmental Specialists

ASSUME THAT INCREMENTAL DISCHARGES OVER THE EMBANKMENT ARE APPROXIMATELY TRIANGULAR IN CROSS-SECTIONAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW (BETWEEN RESERVOIR ELEVATIONS) CAN BE ESTIMATED BY $H_i [(L_1 + L_2) / 2]$, WHERE L_1 = LENGTH AT LOWER ELEVATION, L_2 = LENGTH AT HIGHER ELEVATION, H_i = DIFFERENCE IN ELEVATIONS. THUS, THE TOTAL AVERAGE "FLOW-AREA" WEIGHTED HEAD, H_w , = (TOTAL FLOW AREA / L_2).

EMBANKMENT RATING TABLE:

RESERVOIR ELEVATION (FT)	L_1 (FT)	L_2 (FT)	INCREMENTAL HEAD, H_i (FT)	INCREMENTAL FLOW AREA, A_i (FT ²)	TOTAL FLOW AREA, A_T (FT ²)	WEIGHTED HEAD, H_w (FT)	$\frac{H_w}{L}$	C	Q (CFS)
1503.0	—	0	—	—	—	—	—	—	—
1503.1	0	170	0.1	8.5	8.5	0.1	0.01	2.93	30
1503.2	170	400	0.1	39.5	37	0.1	0.01	2.90	40
1503.3	400	500	0.1	45	82	0.2	0.01	2.97	130
1503.5	500	550	0.2	105	187	0.3	0.02	2.99	270
1503.7	550	600	0.2	115	302	0.5	0.03	3.02	610
1504.0	600	610	0.3	182	484	0.8	0.05	3.03	1320
1505.0	610	635	1.0	615	1099	1.8	0.12	3.04	4550
1506.0	620	650	1.0	635	1734	2.7	0.18	3.07	8520
1507.0	620	670	1.0	635	2359	3.7	0.25	3.08	14200
1508.0	640	680	1.0	650	3009	4.6	0.31	3.09	21400
1510.0	660	670	2.0	1340	4349	6.4	0.43	3.09	34100

① $A_i = H_i \left(\frac{L_1 + L_2}{2} \right)$

② $H_w = A_T / L_2$

③ L = BROADEN OF DAM = 15 FT (FIELD MEASUREMENT)

④ $C = f(H, R)$; FROM REF. 2, FIG. 34

⑤ $Q = CL_2 H_w^{3/2}$

PROJECT DAM SAFETY INSPECTION

PENN NURSERY DAM

BY BJS DATE 1-2-80 PROJ. NO. 79-233-470

CHKD. BY DLB DATE 1-2-80 SHEET NO. 9 OF 12




Engineers • Geologists • Planners
Environmental Specialists

TOTAL FACILITY RATING TABLE

$$Q_{TOTAL} = Q_{SPILLWAY} + Q_{EMBANKMENT}$$

RESERVOIR ELEVATION (FT)	Q _{SPILLWAY} (CFS)	Q _{EMBANKMENT} (CFS)	Q _{TOTAL} (CFS)
1493.0	0	—	0
1494.0	110	—	110
1495.0	340	—	340
1496.0	670	—	670
1497.0	1060	—	1060
1498.0	1480	—	1480
1499.0	1950	—	1950
1500.0	2440	—	2440
1501.0	3000	—	3000
1502.0	3590	—	3590
(LOW TOP OF DAM) 1503.0	4210	0	4210
1503.2	4340 *	40	4380
1503.3	4405 *	130	4535
1503.5	4535 *	370	4905
1503.7	4665 *	640	5305
1504.0	4860	1220	6080
1505.0	5540	4550	10090
1506.0	6240	8580	14820
1509.0	7740	30,130	37,870
1510.0	9340	34,020	43,360


* BY LINEAR INTERPOLATION




GATE OPENING IN FEET

0.1

0







**Engineers • Geologists • Planners
Environmental Specialists**

OVERTOPPING

SUMMARY INPUT/OUTPUT SHEETS

DAM SAFETY INSPECTION
PLAIN MURSELY DAM
EVE-TO-TOE MEASUREMENTS
15-1004 1104 STEP AND 72-0000 STEP DURATION

[illegible]

00-1 69 07- 60
1 = 011111 5 = 011111 1 = 111111
011111 1111 11 11 11 11 11 11 11 11

100

Stur-Akt A KINOT C154P17A11C6

2011年12月10日

[illegible]

PRECIPITATION DATA		INITIAL AND CONSTANT RAINFALL AS PER CODE	
DATE	PRECIPITATION	INITIAL	CONSTANT
01-01-00	0.00	0.00	0.00
02-01-00	0.00	0.00	0.00
03-01-00	0.00	0.00	0.00
04-01-00	0.00	0.00	0.00
05-01-00	0.00	0.00	0.00
06-01-00	0.00	0.00	0.00
07-01-00	0.00	0.00	0.00
08-01-00	0.00	0.00	0.00
09-01-00	0.00	0.00	0.00
10-01-00	0.00	0.00	0.00
11-01-00	0.00	0.00	0.00
12-01-00	0.00	0.00	0.00
01-01-01	0.00	0.00	0.00
02-01-01	0.00	0.00	0.00
03-01-01	0.00	0.00	0.00
04-01-01	0.00	0.00	0.00
05-01-01	0.00	0.00	0.00
06-01-01	0.00	0.00	0.00
07-01-01	0.00	0.00	0.00
08-01-01	0.00	0.00	0.00
09-01-01	0.00	0.00	0.00
10-01-01	0.00	0.00	0.00
11-01-01	0.00	0.00	0.00
12-01-01	0.00	0.00	0.00
01-01-02	0.00	0.00	0.00
02-01-02	0.00	0.00	0.00
03-01-02	0.00	0.00	0.00
04-01-02	0.00	0.00	0.00
05-01-02	0.00	0.00	0.00
06-01-02	0.00	0.00	0.00
07-01-02	0.00	0.00	0.00
08-01-02	0.00	0.00	0.00
09-01-02	0.00	0.00	0.00
10-01-02	0.00	0.00	0.00
11-01-02	0.00	0.00	0.00
12-01-02	0.00	0.00	0.00
01-01-03	0.00	0.00	0.00
02-01-03	0.00	0.00	0.00
03-01-03	0.00	0.00	0.00
04-01-03	0.00	0.00	0.00
05-01-03	0.00	0.00	0.00
06-01-03	0.00	0.00	0.00
07-01-03	0.00	0.00	0.00
08-01-03	0.00	0.00	0.00
09-01-03	0.00	0.00	0.00
10-01-03	0.00	0.00	0.00
11-01-03	0.00	0.00	0.00
12-01-03	0.00	0.00	0.00
01-01-04	0.00	0.00	0.00
02-01-04	0.00	0.00	0.00
03-01-04	0.00	0.00	0.00
04-01-04	0.00	0.00	0.00
05-01-04	0.00	0.00	0.00
06-01-04	0.00	0.00	0.00
07-01-04	0.00	0.00	0.00
08-01-04	0.00	0.00	0.00
09-01-04	0.00	0.00	0.00
10-01-04	0.00	0.00	0.00
11-01-04	0.00	0.00	0.00
12-01-04	0.00	0.00	0.00
01-01-05	0.00	0.00	0.00
02-01-05	0.00	0.00	0.00
03-01-05	0.00	0.00	0.00
04-01-05	0.00	0.00	0.00
05-01-05	0.00	0.00	0.00
06-01-05	0.00	0.00	0.00
07-01-05	0.00	0.00	0.00
08-01-05	0.00	0.00	0.00
09-01-05	0.00	0.00	0.00
10-01-05	0.00	0.00	0.00
11-01-05	0.00	0.00	0.00
12-01-05	0.00	0.00	0.00
01-01-06	0.00	0.00	0.00
02-01-06	0.00	0.00	0.00
03-01-06	0.00	0.00	0.00
04-01-06	0.00	0.00	0.00
05-01-06	0.00	0.00	0.00
06-01-06	0.00	0.00	0.00
07-01-06	0.		

[illegible][illegible]

BASE FLOW PARAMETERS
AS PER ICF

BASEFLOW PARAMETERS
AS PER ICF

REGULATION DATA	
STIRCH	-1.50
ORUSH	-1.00
RICTOR	2.00

UNIT	HYDROCARBON	END-OF-TESTING	ORIGINS, (AGE	3.81	WUORS, CP-	5.50	WU.7	WU
4.	11.	33.	10.	101.	121.	135.	147.	201.
5.	245.	79.	262.	271.	237.	270.	270.	270.
6.	205.	195.	186.	169.	161.	153.	146.	139.
7.	126.	120.	114.	109.	99.	94.	90.	85.
8.	17.	14.	10.	64.	61.	56.	55.	52.
9.	41.	45.	43.	37.	37.	35.	34.	32.
10.	29.	78.	25.	24.	23.	22.	21.	20.
11.	18.	16.	15.	15.	14.	13.	13.	12.
12.	11.	10.	10.	9.	8.	8.	7.	7.
13.	6.	6.	6.	6.	5.	5.	5.	5.

DAM SAFETY INSPECTION

PENN NURSERY DAM

255

1-7-80

79-203-470

DLB

1-7-80

2 OF 6



gai
CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental Specialists

PMF

0.8 PMF

1942-1943. 1944-1945. 1946-1947. 1948-1949. 1950-1951. 1952-1953. 1954-1955. 1956-1957. 1958-1959. 1960-1961. 1962-1963. 1964-1965. 1966-1967. 1968-1969. 1970-1971. 1972-1973. 1974-1975. 1976-1977. 1978-1979. 1980-1981. 1982-1983. 1984-1985. 1986-1987. 1988-1989. 1990-1991. 1992-1993. 1994-1995. 1996-1997. 1998-1999. 2000-2001. 2002-2003. 2004-2005. 2006-2007. 2008-2009. 2010-2011. 2012-2013. 2014-2015. 2016-2017. 2018-2019. 2020-2021. 2022-2023. 2024-2025. 2026-2027. 2028-2029. 2030-2031. 2032-2033. 2034-2035. 2036-2037. 2038-2039. 2040-2041. 2042-2043. 2044-2045. 2046-2047. 2048-2049. 2050-2051. 2052-2053. 2054-2055. 2056-2057. 2058-2059. 2060-2061. 2062-2063. 2064-2065. 2066-2067. 2068-2069. 2070-2071. 2072-2073. 2074-2075. 2076-2077. 2078-2079. 2080-2081. 2082-2083. 2084-2085. 2086-2087. 2088-2089. 2090-2091. 2092-2093. 2094-2095. 2096-2097. 2098-2099. 2100-2101. 2102-2103. 2104-2105. 2106-2107. 2108-2109. 2110-2111. 2112-2113. 2114-2115. 2116-2117. 2118-2119. 2120-2121. 2122-2123. 2124-2125. 2126-2127. 2128-2129. 2130-2131. 2132-2133. 2134-2135. 2136-2137. 2138-2139. 2140-2141. 2142-2143. 2144-2145. 2146-2147. 2148-2149. 2150-2151. 2152-2153. 2154-2155. 2156-2157. 2158-2159. 2160-2161. 2162-2163. 2164-2165. 2166-2167. 2168-2169. 2170-2171. 2172-2173. 2174-2175. 2176-2177. 2178-2179. 2180-2181. 2182-2183. 2184-2185. 2186-2187. 2188-2189. 2190-2191. 2192-2193. 2194-2195. 2196-2197. 2198-2199. 2200-2201. 2202-2203. 2204-2205. 2206-2207. 2208-2209. 2210-2211. 2212-2213. 2214-2215. 2216-2217. 2218-2219. 2220-2221. 2222-2223. 2224-2225. 2226-2227. 2228-2229. 2230-2231. 2232-2233. 2234-2235. 2236-2237. 2238-2239. 2240-2241. 2242-2243. 2244-2245. 2246-2247. 2248-2249. 2250-2251. 2252-2253. 2254-2255. 2256-2257. 2258-2259. 2260-2261. 2262-2263. 2264-2265. 2266-2267. 2268-2269. 2270-2271. 2272-2273. 2274-2275. 2276-2277. 2278-2279. 2280-2281. 2282-2283. 2284-2285. 2286-2287. 2288-2289. 2290-2291. 2292-2293. 2294-2295. 2296-2297. 2298-2299. 2300-2301. 2302-2303. 2304-2305. 2306-2307. 2308-2309. 2310-2311. 2312-2313. 2314-2315. 2316-2317. 2318-2319. 2320-2321. 2322-2323. 2324-2325. 2326-2327. 2328-2329. 2330-2331. 2332-2333. 2334-2335. 2336-2337. 2338-2339. 2340-2341. 2342-2343. 2344-2345. 2346-2347. 2348-2349. 2350-2351. 2352-2353. 2354-2355. 2356-2357. 2358-2359. 2360-2361. 2362-2363. 2364-2365. 2366-2367. 2368-2369. 2370-2371. 2372-2373. 2374-2375. 2376-2377. 2378-2379. 2380-2381. 2382-2383. 2384-2385. 2386-2387. 2388-2389. 2390-2391. 2392-2393. 2394-2395. 2396-2397. 2398-2399. 2400-2401. 2402-2403. 2404-2405. 2406-2407. 2408-2409. 2410-2411. 2412-2413. 2414-2415. 2416-2417. 2418-2419. 2420-2421. 2422-2423. 2424-2425. 2426-2427. 2428-2429. 2430-2431. 2432-2433. 2434-2435. 2436-2437. 2438-2439. 2440-2441. 2442-2443. 2444-2445. 2446-2447. 2448-2449. 2450-2451. 2452-2453. 2454-2455. 2456-2457. 2458-2459. 2460-2461. 2462-2463. 2464-2465. 2466-2467. 2468-2469. 2470-2471. 2472-2473. 2474-2475. 2476-2477. 2478-2479. 2480-2481. 2482-2483. 2484-2485. 2486-2487. 2488-2489. 2490-2491. 2492-2493. 2494-2495. 2496-2497. 2498-2499. 2500-2501. 2502-2503. 2504-2505. 2506-2507. 2508-2509. 2510-2511. 2512-2513. 2514-2515. 2516-2517. 2518-2519. 2520-2521. 2522-2523. 2524-2525. 2526-2527. 2528-2529. 2530-2531. 2532-2533. 2534-2535. 2536-2537. 2538-2539. 2540-2541. 2542-2543. 2544-2545. 2546-2547. 2548-2549. 2550-2551. 2552-2553. 2554-2555. 2556-2557. 2558-2559. 2560-2561. 2562-2563. 2564-2565. 2566-2567. 2568-2569. 2570-2571. 2572-2573. 2574-2575. 2576-2577. 2578-2579. 2580-2581. 2582-2583. 2584-2585. 2586-2587. 2588-2589. 2590-2591. 2592-2593. 2594-2595. 2596-2597. 2598-2599. 2600-2601. 2602-2603. 2604-2605. 2606-2607. 2608-2609. 2610-2611. 2612-2613. 2614-2615. 2616-2617. 2618-2619. 2620-2621. 2622-2623. 2624-2625. 2626-2627. 2628-2629. 2630-2631. 2632-2633. 2634-2635. 2636-2637. 2638-2639. 2640-2641. 2642-2643. 2644-2645. 2646-2647. 2648-2649. 2650-2651. 2652-2653. 2654-2655. 2656-2657. 2658-2659. 2660-2661. 2662-2663. 2664-2665. 2666-2667. 2668-2669. 2670-2671. 2672-2673. 2674-2675. 2676-2677. 2678-2679. 2680-2681. 2682-2683. 2684-2685. 26

PEAK OUTFLOW IS 111.41 11.44 15.00

RESERVOIR
OUTFLOW
HYDROGRAPHS;
OVERTOPPING
OCCURS AT
≈ 0.92 PMF

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL, VOLUME
1	4856	4089	1071	655	188742
2	51	115	53	19	5145
3	12	12	22	23	2160
4	62	308	570	599	599
5	311	311	3900	3900	3900
6	2471	2471	4571	4810	4810

	PLATE	6-BOOK	29-BOOK	72-BOOK	TOTAL VOLUME
1950	3797	4756	1497	525	150950
1951	106	92	15	15	4776
1952		92	42	15	1848
1953		92	1796	1848	47951
1954		1016	92641	47951	3120
1955		1614	7904	3120	4848
1956		1991	4062	3648	4848

REPORT OF DAW SAFETY ANALYSIS						
DATE	TIME OF DAY	LOCATION	TYPE OF INCIDENT	CAUSE	REMARKS	STATUS
10/25/2023	14:30	Room 101	Fire Alarm	Smoke Detector	False Alarm	Resolved
11/05/2023	09:15	Room 202	Water Leak	Plumbing Issue	Minor Leak	Resolved
11/12/2023	16:45	Room 303	Power Outage	Electrical Problem	Outage	Resolved
11/20/2023	08:00	Room 404	Security Breach	Unauthorized Access	Investigation	Pending
12/01/2023	12:30	Room 505	Gas Leak	Gas Valve Issue	Leak	Resolved
12/15/2023	10:00	Room 606	Fire Alarm	Smoke Detector	False Alarm	Resolved
12/22/2023	09:30	Room 707	Water Leak	Plumbing Issue	Minor Leak	Resolved
01/05/2024	07:45	Room 808	Power Outage	Electrical Problem	Outage	Resolved
01/18/2024	11:00	Room 909	Security Breach	Unauthorized Access	Investigation	Pending
01/25/2024	13:15	Room 1010	Gas Leak	Gas Valve Issue	Leak	Resolved
02/02/2024	16:00	Room 1101	Fire Alarm	Smoke Detector	False Alarm	Resolved
02/10/2024	09:30	Room 1202	Water Leak	Plumbing Issue	Minor Leak	Resolved
02/20/2024	14:00	Room 1303	Power Outage	Electrical Problem	Outage	Resolved
03/01/2024	08:15	Room 1404	Security Breach	Unauthorized Access	Investigation	Pending
03/15/2024	12:45	Room 1505	Gas Leak	Gas Valve Issue	Leak	Resolved
03/25/2024	10:30	Room 1606	Fire Alarm	Smoke Detector	False Alarm	Resolved
04/05/2024	15:00	Room 1707	Water Leak	Plumbing Issue	Minor Leak	Resolved
04/15/2024	07:30	Room 1808	Power Outage	Electrical Problem	Outage	Resolved
04/25/2024	11:45	Room 1909	Security Breach	Unauthorized Access	Investigation	Pending
05/05/2024	13:00	Room 2010	Gas Leak	Gas Valve Issue	Leak	Resolved
05/15/2024	16:30	Room 2101	Fire Alarm	Smoke Detector	False Alarm	Resolved
05/25/2024	09:00	Room 2202	Water Leak	Plumbing Issue	Minor Leak	Resolved
06/01/2024	14:15	Room 2303	Power Outage	Electrical Problem	Outage	Resolved
06/10/2024	08:45	Room 2404	Security Breach	Unauthorized Access	Investigation	Pending
06/20/2024	12:00	Room 2505	Gas Leak	Gas Valve Issue	Leak	Resolved
06/30/2024	15:45	Room 2606	Fire Alarm	Smoke Detector	False Alarm	Resolved
07/05/2024	07:15	Room 2707	Water Leak	Plumbing Issue	Minor Leak	Resolved
07/15/2024	11:30	Room 2808	Power Outage	Electrical Problem	Outage	Resolved
07/25/2024	13:45	Room 2909	Security Breach	Unauthorized Access	Investigation	Pending
08/05/2024	16:15	Room 3010	Gas Leak	Gas Valve Issue	Leak	Resolved
08/15/2024	09:45	Room 3101	Fire Alarm	Smoke Detector	False Alarm	Resolved
08/25/2024	14:00	Room 3202	Water Leak	Plumbing Issue	Minor Leak	Resolved
09/01/2024	08:30	Room 3303	Power Outage	Electrical Problem	Outage	Resolved
09/10/2024	12:15	Room 3404	Security Breach	Unauthorized Access	Investigation	Pending
09/20/2024	15:30	Room 3505	Gas Leak	Gas Valve Issue	Leak	Resolved
09/30/2024	07:00	Room 3606	Fire Alarm	Smoke Detector	False Alarm	Resolved
10/05/2024	11:15	Room 3707	Water Leak	Plumbing Issue	Minor Leak	Resolved
10/15/2024	13:00	Room 3808	Power Outage	Electrical Problem	Outage	Resolved
10/25/2024	16:45	Room 3909	Security Breach	Unauthorized Access	Investigation	Pending
11/05/2024	09:30	Room 4010	Gas Leak	Gas Valve Issue	Leak	Resolved
11/15/2024	14:00	Room 4101	Fire Alarm	Smoke Detector	False Alarm	Resolved
11/25/2024	08:15	Room 4202	Water Leak	Plumbing Issue	Minor Leak	Resolved
12/01/2024	12:45	Room 4303	Power Outage	Electrical Problem	Outage	Resolved
12/10/2024	16:00	Room 4404	Security Breach	Unauthorized Access	Investigation	Pending
12/20/2024	07:30	Room 4505	Gas Leak	Gas Valve Issue	Leak	Resolved
12/30/2024	11:00	Room 4606	Fire Alarm	Smoke Detector	False Alarm	Resolved
01/05/2025	15:15	Room 4707	Water Leak	Plumbing Issue	Minor Leak	Resolved
01/15/2025	08:45	Room 4808	Power Outage	Electrical Problem	Outage	Resolved
01/25/2025	12:30	Room 4909	Security Breach	Unauthorized Access	Investigation	Pending
02/05/2025	16:45	Room 5010	Gas Leak	Gas Valve Issue	Leak	Resolved
02/15/2025	09:00	Room 5101	Fire Alarm	Smoke Detector	False Alarm	Resolved
02/25/2025	14:00	Room 5202	Water Leak	Plumbing Issue	Minor Leak	Resolved
03/05/2025	07:45	Room 5303	Power Outage	Electrical Problem	Outage	Resolved
03/15/2025	11:30	Room 5404	Security Breach	Unauthorized Access	Investigation	Pending
03/25/2025	13:15	Room 5505	Gas Leak	Gas Valve Issue	Leak	Resolved
04/05/2025	16:00	Room 5606	Fire Alarm	Smoke Detector	False Alarm	Resolved
04/15/2025	09:30	Room 5707	Water Leak	Plumbing Issue	Minor Leak	Resolved
04/25/2025	14:15	Room 5808	Power Outage	Electrical Problem	Outage	Resolved
05/05/2025	08:00	Room 5909	Security Breach	Unauthorized Access	Investigation	Pending
05/15/2025	12:45	Room 6010	Gas Leak	Gas Valve Issue	Leak	Resolved
05/25/2025	10:30	Room 6101	Fire Alarm	Smoke Detector	False Alarm	Resolved
06/05/2025	15:00	Room 6202	Water Leak	Plumbing Issue	Minor Leak	Resolved
06/15/2025	07:30	Room 6303	Power Outage	Electrical Problem	Outage	Resolved
06/25/2025	11:45	Room 6404	Security Breach	Unauthorized Access	Investigation	Pending
07/05/2025	13:00	Room 6505	Gas Leak	Gas Valve Issue	Leak	Resolved
07/15/2025	16:30	Room 6606	Fire Alarm	Smoke Detector	False Alarm	Resolved
07/25/2025	09:00	Room 6707	Water Leak	Plumbing Issue	Minor Leak	Resolved
08/05/2025	14:15	Room 6808	Power Outage	Electrical Problem	Outage	Resolved
08/15/2025	08:45	Room 6909	Security Breach	Unauthorized Access	Investigation	Pending
08/25/2025	12:00	Room 7010	Gas Leak	Gas Valve Issue	Leak	Resolved
09/05/2025	15:45	Room 7101	Fire Alarm	Smoke Detector	False Alarm	Resolved
09/15/2025	07:15	Room 7202	Water Leak	Plumbing Issue	Minor Leak	Resolved
09/25/2025	11:30	Room 7303	Power Outage	Electrical Problem	Outage	Resolved
10/05/2025	13:45	Room 7404	Security Breach	Unauthorized Access	Investigation	Pending
10/15/2025	16:15	Room 7505	Gas Leak	Gas Valve Issue	Leak	Resolved
10/25/2025	09:45	Room 7606	Fire Alarm	Smoke Detector	False Alarm	Resolved
11/05/2025	14:00	Room 7707	Water Leak	Plumbing Issue	Minor Leak	Resolved
11/15/2025	08:30	Room 7808	Power Outage	Electrical Problem	Outage	Resolved
11/25/2025	12:15	Room 7909	Security Breach	Unauthorized Access	Investigation	Pending
12/01/2025	15:30	Room 8010	Gas Leak	Gas Valve Issue	Leak	Resolved
12/10/2025	07:00	Room 8101	Fire Alarm	Smoke Detector	False Alarm	Resolved
12/20/2025	11:00	Room 8202	Water Leak	Plumbing Issue	Minor Leak	Resolved
12/30/2025	15:45	Room 8303	Power Outage	Electrical Problem	Outage	Resolved
01/05/2026	07:15	Room 8404	Security Breach	Unauthorized Access	Investigation	Pending
01/15/2026	12:45	Room 8505	Gas Leak	Gas Valve Issue	Leak	Resolved
01/25/2026	10:30	Room 8606	Fire Alarm	Smoke Detector	False Alarm	Resolved
02/05/2026	14:00	Room 8707	Water Leak	Plumbing Issue	Minor Leak	Resolved
02/15/2026	08:15	Room 8808	Power Outage	Electrical Problem	Outage	Resolved
02/25/2026	12:30	Room 8909	Security Breach	Unauthorized Access	Investigation	Pending
03/05/2026	16:45	Room 9010	Gas Leak	Gas Valve Issue	Leak	Resolved
03/15/2026	09:00	Room 9101	Fire Alarm	Smoke Detector	False Alarm	Resolved
03/25/2026	14:00	Room 9202	Water Leak	Plumbing Issue	Minor Leak	Resolved
04/05/2026	07:45	Room 9303	Power Outage	Electrical Problem	Outage	Resolved
04/15/2026	11:30	Room 9404	Security Breach	Unauthorized Access	Investigation	Pending
04/25/2026	13:15	Room 9505	Gas Leak	Gas Valve Issue	Leak	Resolved
05/05/2026	16:00	Room 9606	Fire Alarm	Smoke Detector	False Alarm	Resolved
05/15/2026	09:30	Room 9707	Water Leak	Plumbing Issue	Minor Leak	Resolved
05/25/2026	14:15	Room 9808	Power Outage	Electrical Problem	Outage	Resolved
06/05/2026	08:00	Room 9909	Security Breach	Unauthorized Access	Investigation	Pending
06/15/2026	12:45	Room 10010	Gas Leak	Gas Valve Issue	Leak	Resolved

THEY ARE USED AS A BASIS FOR THE CALCULATION OF THE FOLLOWING RESULTS: APPROXIMATELY 0.92 PMF

LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army, Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer, Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulic, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt, McGraw-Hill, Inc., New York, 1968.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965.
10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army, Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army, Corps of Engineers, Pittsburgh District.


12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.
16. Water Resources Engineering, R. K. Linsley and J. B. Franzini, McGraw-Hill, Inc., New York, 1972.
17. Engineering for Dams, Volume 2, W. P. Creager, J. D. Justin, J. Hinds, John Wiley & Sons, Inc., New York, 1964.

APPENDIX E

FIGURES

LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	Regional Vicinity and Watershed Boundary Map
2	General Plan
3	Profiles and Typical Cross Sections
4	Spillway Details I
5	Spillway Details II




AMS 5465 I SW-SERIES V831


REGIONAL VICINITY AND WATERSHED BOUNDARY MAP

ST WATERCOURSE
DID OF DRAINAGE AREA


AMS 5465 I SE-SERIES V831










gai
CONSULTANTS, INC.
FIGURE 2














APPENDIX F

GEOLOGY

Geology


Penn Nursery Dam is located in the Appalachian Mountain Section of the Valley and Ridge physiographic province of central Pennsylvania. This region is characterized by a series of northeast-southwest trending parallel mountains and intermontane valleys. Intense lateral compression from the southeast produced a series of high amplitude anticlines and synclines in the formerly flat lying strata. Folding of the rock strata was followed by uplift. Subsequent erosion cut valleys in the softer, less resistant beds and left the harder resistant strata as high mountain ridges.

Penn Nursery Dam is located on Potter Run in Triester Valley which is flanked on the northwest by Triester Mountain and on the southeast by Sand Mountain. Structurally, the dam and reservoir are located in a tightly folded area with plunging syncline and anticline complexes.

Bedrock underlying the dam consists of "interbedded dark-gray, shale and thin gray sandstone beds" representing the Reedsville Formation of Ordovician age. Bedding dips approximately 15 degrees. Separations along bedding and cleavage, which dips at about 80 degrees are the dominant fracture planes. The upper 2 to 8 feet of rock is highly fractured with moderate fracturing occurring with depth. A weathered zone of fragmental shale, partly decomposed and ranging in thickness from 1 to 3 feet overlies the relatively fresh rock."

"Along the proposed dam axis and above a surface elevation of approximately 1,502 feet, the overburden consists predominantly of brown silty fine sand. In the lower, central part of the stream valley, along the dam axis, the overburden consists of layers of clayey silt, silty sand and gravel and clayey silt with gravel. These sediments represent floodplain deposits of Potter Run".

¹Rose, C. W. et. al., "Subsurface Exploration, Penn Nursery Irrigation Dam, Potler Stream, Centre County, Pennsylvania".



LEGEND

SILURIAN

Keyser Formation

Dark gray, highly fossiliferous, thick bedded, crystalline to nodular limestone passes into Martins, Rondout, and Decker Formations in the east

Tonoloway Formation

Gray, highly laminated, thin bedded, argillaceous limestone, passes into Rossburgville and Pozono Island beds in the east

Wills Creek Formation

Greenish gray, thin bedded, fossiliferous shale with local limestone and sandstone zones, contains red shale and siltstone in the lower part

Bloomsburg Formation

Red, thin and thick bedded shale and siltstone with local units of sandstone and thin impure limestone, some green shale in places

Clinton Group

Predominantly Rose Hill Formation - Reddish purple to greenish gray, thin to medium bedded, fossiliferous shale with intertonguing "iron sandstones" and local gray, fossiliferous limestone; above the Rose Hill is brown to white quartzitic sandstone (Kiefer) interbedded upward with dark gray shale (Rochester)

Tuscarora Formation

White to gray, medium to thick bedded, fine grained, quartzitic sandstone, conglomeratic in part

ORDOVICIAN

CENTRAL PENNSYLVANIA

Juniata Formation

Red, fine grained to conglomeratic, quartzitic sandstone with well developed cross-bedding and with interbedded red shale in places

Bald Eagle Formation

Gray to greenish gray, fine grained to conglomeratic, thick bedded sandstone; often iron-speckled and cross-bedded; some greenish gray shale in places

Reedsville Formation

Dark gray, olive weathering shale with thin silty to sandy interbeds; black shale of Antes Formation at the base

Coburn Formation

Dark gray to black, thin bedded limestone with black shale interbeds

Salona Formation

Dark gray, thin bedded, dense limestone

Nealmont Formation

Bluish gray, finely crystalline, fossiliferous limestone, lower part grades laterally into Curtin Formation

Curtin Formation

Gray, impure limestone, bluish gray, fine grained, high calcium limestone with some larger calcite grains (Valentine Member, Ovi at the top)

Benner Formation

Gray, mottled, dolomitic limestone and coarse granular limestone

Hatter Formation

Dark gray, impure, fossiliferous limestone


Loysburg Formation

Dense limestone over irregularly banded dolomitic limestone

Bellefonte Formation

Gray, cream to tan weathering, medium bedded dense dolomite

Scale



REFERENCE:

GEOLOGIC MAP OF PENNSYLVANIA PREPARED BY COMMONWEALTH OF PENNA. DEPT. OF INTERNAL AFFAIRS, DATED 1960, SCALE 1" = 4 MILES

GEOLOGY MAP

gai
CONSULTANTS, INC.